



## Who Should Build This Kit?

The H32 is not difficult to build, but it is not intended for absolute beginners. If you've never built an electronic project before, this is probably not the one to start with. To guarantee success, make sure you have:

- The ability to make basic voltage and resistance measurements using a digital multimeter (DMM).
- At least a rudimentary understanding of voltage, current, and resistance.
- Some experience soldering on printed circuit boards.
- The patience to follow instructions precisely and work carefully.

## Essential Tools

Fine tipped, 20-30 watt soldering iron w/ cleaning sponge (Hakko 936 or similar)  
Eutectic (63/37) rosin core or "no clean" solder (.025" diameter or smaller is best)  
Good-quality DMM  
Small needle nose pliers  
Small diagonal cutters  
Phillips screwdriver (#1)  
Precision straight blade screwdriver (for adjusting potentiometers)

## Highly Recommended Tools

Lead bender (Mouser 5166-801)  
T-Handle wrench and 4-40 tap (Hanson 12001 and 8012)  
MOLEX crimp tool (Waldom W-HT1919 or equivalent)  
Magnifying glass

## Optional Tools

Panavise w/ circuit board head  
Oscilloscope  
Signal generator

## Work Area

Find a clean, flat, stable, well-lit surface on which to work. An anti-static mat is recommended for this project. If you're in a dry, static-prone environment, it's essential. The importance of good lighting can't be overstated. Component markings are tiny, and you'll be deciphering a lot of them.

## Soldering Technique

Make sure your iron's tip is tinned properly and keep it clean! The trick to making perfect solder joints is to heat the joint quickly and thoroughly before applying the solder, and a properly tinned and clean tip is essential for this. Apply enough solder to form a "fillet" between the lead and the pad, a little mound of solder that smoothly transitions from the plane of the board up to the lead, **but don't use too much**. The finished joint should be smooth and shiny, not rough or gritty looking.

If you've never soldered a board with plated-through holes, you might be surprised to discover how difficult it can be to remove a component once you've soldered it in place. If you're using solder wick to correct a mistake, be very careful not to overheat the pads, since they will eventually delaminate and "lift". It's often better to sacrifice the component and remove its leads individually and start over with a new part. If for some reason you need to unsolder a multipin component (like a rotary switch or integrated circuit), remove as much solder as you can with solder wick or a solder sucker, and then use a small heat gun to heat all the leads simultaneously. With care, you can remove the component without damaging the board.


## Instruction Conventions

Text in **orange** indicates a step where extra care needs to be taken. Doing it wrong isn't a disaster, but it'll need to be corrected.


Text in **red** indicates a step that **must** be done correctly. Doing it wrong will guarantee improper operation, and probably damage components and/or the circuit board.

## Assembly


1. Before you begin, carefully unpack the kit and examine the parts. Check the contents of each small bag against the BOM to make sure all the parts have been included. If you think something's missing, please e-mail the details to [sales@seventhcircleaudio.com](mailto:sales@seventhcircleaudio.com) and we'll ship replacement parts ASAP.
2. Generally, the idea when "stuffing" or "populating" a circuit board by hand is to start with the lowest profile parts, such as the resistors, and work your way up to the taller components. In each step below, insert the components, flip the board onto your work surface component-side down, and carefully solder and trim the leads. Use a piece of stiff cardboard to hold the parts in place while you flip the board. First, orient the board as shown.



3. Before installing the resistors, prepare the leads using small needle nose pliers or a lead-forming tool as shown below. **Whatever you do, don't bend the leads at the resistor body and force them into the board.** This not only results in an ugly job, it can also damage the parts.




4. Insert the 1/4-watt resistors. Check the Bill of Materials (BOM) for help in reading the resistor color bands. It's also a good idea to actually measure each resistor with your DMM as you place it on the board, just in case you've decoded it incorrectly. Don't rely on the photos for component placement. **THE PCB PICTURES ARE NOT NECESSARILY THE CURRENT REVISION OR EVEN THE CORRECT MODEL!** If the resistor value silkscreened on the board doesn't agree with the value on the schematic or parts list, follow the schematic.




5. Next, add the protection diodes. **Diodes are polarized and must be installed the right way around!** The colored band on the diode matches the white band on the silkscreen.


6. Add the small yellow ceramic capacitors. These capacitors are not polarized and can be installed in either direction, **but pay close attention to the capacitor markings!** These parts all look alike, but they are not interchangeable. Putting one in the wrong spot will not prevent the preamp from passing signal, but it can seriously impair its performance.



7. Install U1, U2, U3 and U4 now. **Pay close attention to the IC markings. Align the notch on the IC with the notch on the silkscreen outline!** IC sockets are **not** included in the kit and are **not** recommended. Socketing the ICs will interfere with the ability of the PC board to conduct heat away from the parts.




8. Install the 1uF film caps at C7, C8 and C15. These parts are not polarized and can be installed in either direction.




9. Add the electrolytic capacitors now. C13 and C17 are not polarized, but the rest are **and must be installed the right way around!** Be absolutely sure to observe the correct polarity when installing these parts. The **negative leads** of the electrolytic caps are marked with a colored stripe. The **positive pads** on the circuit board are marked with a small "+" sign.




- Carefully mount the toggle switches SW101 and SW201. Be sure they're seated flat on the board before soldering all the pins. You may find it easier to solder the first pin with the board component side up.




- Add J301, the MOLEX power connector. Be sure to orient it as shown, with the locking tab away from the edge of the board.




- Using the hardware supplied, attach heat sinks to U301 and U302 and solder them in place. **Make sure to install the regulators correctly!** These parts are not the same and are not interchangeable.




- Install rotary switches. Make sure the switches are fully seated and solder them to the board. Try to make your solder joints as neat as possible, and don't use too much solder.






14. Add CONN1 and CONN2 to the board. Make sure they're fully seated before soldering.



15. Install the bulk filter capacitors C302 and C305. Push them in firmly until they are fully seated against the board. Again, **electrolytic capacitors are polarized and must be installed the right way around!** Be absolutely sure to observe the correct polarity when installing these parts.



16. Before going on to initial power-up, carefully check your work. Make sure you haven't created any solder bridges between pads, or between a pad and the ground plane.

## Initial Power-Up and Testing.

17. Again, carefully check your work. Make sure you've got the right resistors in the right locations. Make absolutely sure you've got all the transistors, diodes, and capacitors soldered in the right way around! Double check to make sure you haven't inadvertently swapped a transistor or voltage regulator. Check for poor solder joints and solder bridges, and make sure you fix any problems before continuing.
18. Just to make sure you haven't created any blatant shorts, measure the resistance between pins 1 and 2 of J301. Do the same for pins 3 and 2. If you measure a steady resistance of less than 100 ohms, don't apply power. Carefully check your work until you *find that short*.
19. Connect the PS03 to J301 on the H32 using a WH01 wire harness or similar. Verify that there are no crossed wires or loose crimps in the harness. Be sure the locking ramps engage.
20. Set your DMM to measure DC voltages of 2V or greater and turn on the power. Clip the negative meter probe to PGND and measure the voltage at the +V test point at D303. You should see about +18V.
21. With the negative probe still connected to PGND, measure the -V test point at D306. You should see about -18V.
22. If the voltages measured in the two previous steps are off by more than a volt or so, you have problems. Possible things to check are incorrectly installed diodes, backwards caps or shorts around U301, and U302.
23. Congratulations! You've got a working H32 preamp.

